Inspection Report

Name of Work	:	Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.
Work Order	:	EE/BTP/BBMP/KRIDL/WO/460/2013-14 Dated: 21.02.2014.
Agency	:	Technical Managara (West), KRIDL
B.R. No & Date	:	72/13-14 Dated: 31.05.2014
Bill Amount	:	19,92,031.46
Job Code	:	009-14-000050
P. Code	:	P-2434
Date of Inspection	:	11-09-15

the above said Work at Bore Well at Vidyaranyapura Area in Ward No 09 Vidyaranyapura has been shown by the Concerned AE. the above said work has been inspected along with the Concerned JE the Bore wells has been drilled.

1. Dodda Chinnappa Layout
2. Nagarjuna
3. Durgaparameshwari Layout.

the Bore well drilled at Durgaparameshwari Layout is failed and abdonned due to Silt formation. the Bore well drilled at Dodda Chinnappa layout and Nagarjuna is Successful and the water supply to the Residents of the Vicinity

P.T.O.

Executive Engineer
Byatarayanapura Division
Yelahanka Zone, B.B.M.P.

V.G.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTO)
PUBLIC WORKS DEPARTMENT

of the Two Bore Wells is running smoothly. The connected Records pertains to the Bore wells and the "Lesson" is Verified.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

152 - BYATARAYANAPURA AC
WARD NAME : 9 - VIDYARANYAPURA



Note:

(1) Bore well No. 2 - in durga layout failed due to less yield.

(2) BW-2 pump-motor not fixed and the demo is fixed to Existing Bore No. BW4 at Badara Mahi - 2nd Cross.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.

Assistant Engineer
Ward No. 09

2 Doddabommandra, Narayana Hounde Road

Photos Showing the Work of Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.



Assistant Engineer
Ward No. 09

EXECUTIVE ENGINEER (CIVIL)
PUBLIC WORKS DEPARTMENT

Nanjapura

Photos Showing the Work of Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.

Assistant Engineer
Ward No. 09

"Durgaparameshwari Main Road"

EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Assistant Engineer
Ward No. 09

Pump motor Installed to Bore by B.W.S at Banana Country Layout 1st Cross in Ward no.09

Photos Showing the Work of Borewells at Vidyaranyapura Area in Ward No. 09 (Vidyaranyapura), Vidyarnyapura Sub Division.

Assistant Engineer
Ward No. 09

EXECUTIVE ENGINEER
PUBLIC WORKS DEPARTMENT

Basava Samithi layout in W-09 - 1st Cross
Near Nandi Bakery,